

Smits, Marc P CIV NAVFAC SW

From: Quang Than [QThan@dtsc.ca.gov]
Sent: Friday, October 31, 2008 6:28 PM
To: Smits, Marc P CIV NAVFAC SW
Cc: Manny Alonzo; Quang Than; Arnold, Content P CIV NAVFAC SW; Theroux, Debra M CIV OASN (I&E) BRAC PMO West
Subject: RE: RTCs, PRL 747, Draft Summary Report for Group V PRLs, EBS, Former MCAS El Toro

Hi Marc,

Thanks for the clarifications. DTSC has no further comments and concurs with the No-Further-Investigation recommendation for PRL 747. Please call if you have any questions.

Thanks,
Quang

>>> "Smits, Marc P CIV NAVFAC SW" <marc.smits@navy.mil> 10/28/2008 1:08 PM >>>
Quang-

Attached are responses to your follow-on comments presented below. We can discuss further tomorrow at the BCT meeting if you require further clarification.

Thanks-

Marc P. Smits PE
Remedial Project Manager
Marine Corps/Mare Island Team

-----Original Message-----

From: Quang Than [mailto:QThan@dtsc.ca.gov]
Sent: Friday, October 24, 2008 18:19
To: Smits, Marc P CIV NAVFAC SW
Cc: Arnold, Content P CIV NAVFAC SW
Subject: Re: Response to Comment - Draft Summary Report for Group VPRLs, EBS, Former MCAS El Toro

Hi Marc,

I have some follow-up questions on this and they are as follow:

1. The depth of samples at HA-1 and HA-2 is listed at 2.5 feet bgs. Is this the true 2.5 feet bgs or 2.5 feet from the top of the concrete pad?

Do you have information on the thickness of the concrete and the thickness of the foundation of the concrete pad?

2. The same question goes for the sump boring location, i.e. the true depth of the two samples from HA-3, if different from the listed one.

3. In the figure I noticed a stain on the ground surface immediately west of the concrete pad. Do you know why that spot was not selected for a boring location?

Please get back with me at your earliest opportunity. And call me if you have any questions.

Thanks,
Quang

>>> "Smits, Marc P CIV NAVFAC SW" <marc.smits@navy.mil> 10/7/2008 4:20 PM >>>

Quang-



Attached is the response to comment related to PRL 747 from the Group V Summary Report submitted in July 2008. Please review the response to comment and give me a call to discuss.

Thanks-

Marc P. Smits PE
Remedial Project Manager
Marine Corps/Mare Island Team

<<DTSC_RTCs_68sr_dft_grpV.doc>>